




cable parts

Figure 3






- ring to the fixing sleeve.
- | 2. Arrange the shielding wire as shown in the figure above.



1. Use the clamping ring to divide the shielding wire into 4-6 groups, then buckle the clamping ring onto the shielding ring. 2. Rotate the clamping ring to wrap the shielding wire around the shielding ring.



1. After installing the core cable parts press it into the plug body, tighten it with the compression nut by a torque of 4-6N. 2. The final installation will be as shown in the figure above.

https://www.weipuconnector.com/